

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/18/2019

Submitted Date:

04/18/2019

Document Number:

696100803**FIELD INSPECTION FORM**Loc ID 310232 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections
,		dnr_cogccengineering@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291652	WELL	SI	04/01/2017	GW	123-26107	70 RANCHUSX BB 35-03	PA

General Comment:This is a **PLUGGED & ABANDONED WELL, ABANDONED BATTERY** Inspection.

Well: PA

Battery: Abandoned & most equipment removed except for gas meter run & riser.

Abandoned Battery SE corner GPS coordinates: 40.360624, -104.406738

Reclamation progressing.

Location**Lease Road:**

Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:			

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused gas meter run, riser, & equipment at Abandoned Battery site. Refer to Rule 603.f for guidance when machinery required to remove equipment. See photos #2, 3.		
Corrective Action:	Remove unused gas meter run, riser, & equipment at Abandoned Battery site. Comply w/ Rule 603.f.	Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 291652 Type: WELL API Number: 123-26107 Status: SI Insp. Status: PA

Idle WellPurpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Well appears to have been P&A.
 Form 6 #401732256 indicates plugging date: 06/29/2018. (Approval Pending).
 Reclamation progressing.

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>On THU APR 18, 2019 at approximately 13:30 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: 70 RANCHUSX BB-65N63W /35NENW Location ID: 310232 Location County: Weld County, Colorado While there, I observed: 1-Well(s) PA & Abandoned Battery . Routine Inspection.</p> <p>1 - Corrective Actions observed. 1.) Unused gas meter run, riser, & equipment at Abandoned Battery site. Refer to Rule 603.f for guidance when machinery required to remove equipment. See photos #2, 3. Remove unused gas meter run, riser, & equipment at Abandoned Battery site. Comply w/ Rule 603.f.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	04/18/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696100804	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4800512