

Laramie Energy LLC
Api # 05-077-10104
Inspection # 675002196



**Photo of Wellheads with soil stain,
Full white chemical container and containment removed.**

Laramie Energy LLC
Api # 05-077-10104
Inspection # 675002196



Photo of Wellheads with soil stain,
Full white chemical container and containment removed.



Unmarked riser by wellhead