

Inspection Photos
Operator: BP America
Location/API #: 067-07379
Date: 4-12-2019



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward.



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of musk thistle (*Carduus nutans*) rosettes within the interim reclamation area.



Photo 5. View of kochia debris along the southeastern edge of the working area.