

Final Reclamation and Stormwater Inspection

April 12, 2019

Operator: KERR MCGEE OIL & GAS # 47120

Location ID: 329527

Inspection Document #: 674902786

Weld County, CO

NESW Section 14 T1N R66W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: KERR MCGEE /1N66W14
Location ID: 329527



Photo 1. Photo taken from the access road, facing West. Appears Operator has performed final reclamation activities at the location with evidence of drilling rows. However along the access road the reclamation is not at percent cover and has non-uniform establishment of vegetation cover.



Photo 2. Photo taken from the access road, facing East. See comments from Photo 1.

Inspection Photos
Location Name: KERR MCGEE /1N66W14
Location ID: 329527



Photo 3. Photo taken looking into the location, facing Northeast. Appears Operator has performed final reclamation activities at the location with evidence of drilling rows and straw crimped mulch.



Photo 4. Photo taken looking into the location, facing Northeast. See comments from Photo 3.