

# Final Reclamation and Stormwater Inspection

April 12, 2019

Operator: KERR MCGEE OIL & GAS # 47120

Location ID: 305428

Inspection Document #: 674902788

Weld County, CO

SWSE Section 13 T1N R66W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: KERR MCGEE /1N66W13

Location ID: 305428



**Photo 1.** Photo taken from the access road off CR 8, facing Northeast. Appears Operator has performed final reclamation activities at the access road and facility with the evidence of drill rows, straw crimped mulch and some revegetation. However, parts of the reclamation is not at percent cover and has non-uniform establishment of vegetation cover.



**Photo 2.** Photo taken from the existing land owner access road looking towards the location, facing North. Appears Operator has performed final reclamation activities at the location and northern part of the access road with the evidence of drill rows matching the adjacent cropland.

Inspection Photos  
Location Name: KERR MCGEE /1N66W13  
Location ID: 305428



**Photo 3.** Photo taken from the location, facing North.  
See comments from Photo 2.



**Photo 4.** Photo taken from the location, facing South.  
See comments from Photo 2.