

# Final Reclamation and Stormwater Inspection

April 12, 2019

Operator: KERR MCGEE OIL & GAS # 47120

Location ID: 318069

Inspection Document #: 674902789

Weld County, CO

SWSW Section 18 T1N R65W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: KERR MCGEE /1N65W18  
Location ID: 318069



**Photo 1.** Photo taken from the access road off CR 37, facing West. Appears the access road remains off CR 37.



**Photo 2.** Photo taken from the access road, facing Southeast. See comments from Photo 1.

Inspection Photos  
Location Name: KERR MCGEE /1N65W18  
Location ID: 318069



**Photo 3.** Photo taken from the access road, facing Southeast. Appears a two-track still remains along the access road.



**Photo 4.** Photo taken from the location, facing Northwest. See comments from Photo 3.



Inspection Photos  
Location Name: KERR MCGEE /1N65W18  
Location ID: 318069



**Photo 5.** Photo taken from the location, facing North. Appears Operator has performed final reclamation activities at the location with the evidence of revegetation.



**Photo 6.** Photo taken from the location, facing East. See comments from Photo 5.