

Inspection Photos

Loc#335146

Operator: Terra

Inspection Number: 692400905

Inspection Date: 4/15/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Southwest.

April 15, ,2019




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Clough RWF Loc#335146



Photo#2:
View over Pit to Northwest.

April 15, ,2019



Photo#3:
View over Pit to Southeast.



Photo#4:
Wattles have been installed as perimeter Controls.

April 15, ,2019



Photo#5:
Pieces of Debris at NW end of Well lineup.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Clough RWF Loc#335146



Photo#6:
Sediment traps have been have been roughed in.

April 15, ,2019



Photo#7:
Sediment traps have been have been roughed in.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Clough RWF Loc#335146



Photo#8:
BMPs at South corner of undisturbed (for construction expansion) area of site need maintenance.

April 15, 2019



Photo#9:
BMPs at South corner of undisturbed (for construction expansion) area of site need maintenance.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Clough RWF Loc#335146