

Laramie Energy LLC  
Api # 05-077-10578  
Inspection # 675002198



04.19.2019

Photo at entrance of location

Laramie Energy LLC  
Api # 05-077-10578  
Inspection # 675002198



Photo of location at entrance

Laramie Energy LLC  
Api # 05-077-10578  
Inspection # 675002198



Tank battery

Photos of wellheads

Laramie Energy LLC  
Api # 05-077-10578  
Inspection # 675002198



**BMP in need of maintenance**

**BMP in need of maintenance**

Laramie Energy LLC  
Api # 05-077-10578  
Inspection # 675002198



**Drill cuttings dumped outside of location Berm**