

**Laramie Energy LLC**  
**Api # 05-077-08850**  
**Inspection # 675002206**



**Photo at entrance, Battery sign contains past operator information.**

**Laramie Energy LLC**  
**Api # 05-077-08850**  
**Inspection # 675002206**



**Photo of location at entrance. .**



**Laramie Energy LLC**  
**Api # 05-077-08850**  
**Inspection # 675002206**



**Tank battery**



**Wellhead on location**

**Laramie Energy LLC**  
**Api # 05-077-08850**  
**Inspection # 675002206**



**Holes in tank containment liner**



**Holes in tank containment liner**



**Laramie Energy LLC**  
**Api # 05-077-08850**  
**Inspection # 675002206**



**No BMP's for piled up soil on location.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Laramie Energy LLC**  
**Api # 05-077-08850**  
**Inspection # 675002206**



**Wellhead sign**



**Frac tank containment good**



Laramie Energy LLC  
Api # 05-077-08850  
Inspection # 675002206



Operation equipment, All equipment in containment.



Top of wellhead

**Laramie Energy LLC**  
**Api # 05-077-08850**  
**Inspection # 675002206**



**Unused tanks remains stored on location.**



**Heavy erosion of soil moving off location**



**Laramie Energy LLC**  
**Api # 05-077-08850**  
**Inspection # 675002206**



**Erosion and sediment moving off location at entrance. BMP need maintenance**



**Heavy erosion of soil moving off location Dirt berm not contained by BMP**



**Laramie Energy LLC**  
**Api # 05-077-08850**  
**Inspection # 675002206**



**Heavy erosion of soil moving off location No BMP in place.**



**Heavy erosion moving soil off location.**