

Location Name: Beren Corporation – Brewer A (Rem #10290 – North Pit)  
Inspection Date: 4/17/2019



Photo # - 1

View east across excavation west of MW06 and former north production pit



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Beren Corporation – Brewer A (Rem #10290 – North Pit)

Inspection Date: 4/17/2019



Photo # - 2

Stained soil in excavation



Location Name: Beren Corporation – Brewer A (Rem #10290 – North Pit)  
Inspection Date: 4/17/2019



Photo # - 3

Stained soil in northeast of MW06

Location Name: Beren Corporation – Brewer A (Rem #10290 – North Pit)  
Inspection Date: 4/17/2019



Photo # - 4

Stained soil in north of MW06

Location Name: Beren Corporation – Brewer A (Rem #10290 – North Pit)

Inspection Date: 4/17/2019



Photo # - 5

Stained soil in the former location of MW06



Location Name: Beren Corporation – Brewer A (Rem #10290 – North Pit)

Inspection Date: 4/17/2019



Photo # - 6

Free product entering the excavation from the former location of MW06



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Beren Corporation – Brewer A (Rem #10290 – North Pit)  
Inspection Date: 4/17/2019



Photo # - 7

Free product accumulating in the excavation from the former location of MW06



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Beren Corporation – Brewer A (Rem #10290 – North Pit)  
Inspection Date: 4/17/2019



Photo # - 8

Free product accumulating in the excavation from the former location of MW06

