

## Inspection Photos

Location Name: TRAIL CANYON 24-3

Location ID: 05-103-10962

Inspection: 679703834



**Photo 1. Location looking northeast.**



**Photo 2. Tank without label.**



## Inspection Photos

Location Name: TRAIL CANYON 24-3

Location ID: 05-103-10962

Inspection: 679703834



**Photo 3. Gas leaking through valve.**



**Photo 4. Gas rate measured with 3 cubic ft bag.**



## Inspection Photos

Location Name: TRAIL CANYON 24-3

Location ID: 05-103-10962

Inspection: 679703834

Gas leaking



Photo 5. Gas leaking adjacent to separator building.

Photo 6. Gas leaking adjacent to separator building.



## Inspection Photos

Location Name: TRAIL CANYON 24-3

Location ID: 05-103-10962

Inspection: 679703834



**Photo 7. Weed debris on location.**



## Inspection Photos

Location Name: TRAIL CANYON 24-3

Location ID: 05-103-10962

Inspection: 679703834



**Photo 8. Storm water channels coming from location down the lease road.**



**Photo 9. Storm water channel from location going into the Gillam Draw flowing water.**

