

Inspection Photos
Location Name: NGL /C9B
Location #: 440284



Photo #1

NGL C9B (05-123-40770) Injection Wellsite

Shut-In | SI



Photo #2

NGL C9B Injection Well

Shut-In | SI

Stained soil



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: NGL /C9B
Location #: 440284



Colorado Oil & Gas Conservation Commission
40.83616, -104.16395, 1524.0m, 123°
04/22/2019 01:59:31 PM

Photo #3

NGL C9, C9-B, C9-C Facility Entrance

C9: Active Injection, C9-B: SI

C9-C: Post repair MIT, pass



Colorado Oil & Gas Conservation Commission
40.83651, -104.16248, 1526.0m, 154°
04/22/2019 03:22:54 PM

Photo #4

NGL C9, C9-B, C9-C Facility Tanks



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: NGL /C9B
Location #: 440284



Photo #5
NGL C9, C9-B, C9-C Injection Pump Room

