

Inspection Photos

API# 103-01123

Operator: C&J Field Services

Inspection Number: 692400855

Inspection Date: 3/28/19





Photo#1:
View to North over Location.



Photo#2:
View to South from access road into Location.

March 28, 2019



Photo#:3
Area approx. 24'X20' of what appears to be black stained soil which retains smell of petroleum.

March 28, 2019



Photo#4:
Close up of soil in Photo#3



Photo#5:

Utility installation (electric?) is in place and appears to have wire run through draw & ties into Utility Box of PR Well API#103-07931.

March 28, 2019



Photo#6:



Photo#5:

Utility installation (electric?) is in place and appears to have wire run through draw & ties into Utility Box of PR Well API#103-07931.

Photo#6:

March 28, 2019