

Maralex Resources Inc.
Api # 05-077-08493
Inspection # 675002210



Photo at entrance of location.

Maralex Resources Inc.
Api # 05-077-08493
Inspection # 675002210



Photo of tank battery. Berm needs maintenance, Debris in Containment, labels need all current operator information

Maralex Resources Inc.
Api # 05-077-08493
Inspection # 675002210



Photo at wellhead

Maralex Resources Inc.
Api # 05-077-08493
Inspection # 675002210



Pit fence in need of repair



Equipment photo

**Maralex Resources Inc.
Api # 05-077-08493
Inspection # 675002210**



Tank berm in need of maintenance, debris in containment. .



Tank labels , wrong contact information.