

Inspection Photos  
Location Name: Schmier B 32-32  
Location ID: 302380



Photo 1: Wellhead (TA)



Photo 2: Centralized Tank Battery

**Inspection Photos**  
**Location Name: Schmier B 32-32**  
**Location ID: 302380**



**Photo 1: North separator (stained soil)**



**Photo 4: Unused equipment**