

Inspection Photos
Location Name: McCallum Unit 39
API: 05-057-06013



Photo 1. Overview of location taken at entrance facing southwest.



Photo 2. Non reportable spill. Stained soil at wellhead.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 689802535