

Inspection Photos

4/24/2019

Operator: BENCHMARK ENERGY LLC - 10380

Location ID: 312205

Inspection Doc. Number: 682504801

Logan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: BENCHMARK ENERGY LLC - 10380
Location ID: 312205



Photo 1: Photo taken from the south end of the location, facing west. Photo provides overview of the location.



Photo 2: Photo taken from the well. Photo shows undesirable weedy plant species such as kochia and salsola sp. Have established on areas adjacent to well head. Other plant species such as Curly dock evident.

What appears to be Canada thistle rosettes evident at the well head. This is a Colorado State listed noxious weed.

Inspection Photos
Operator: BENCHMARK ENERGY LLC - 10380
Location ID: 312205



Photo 3: Photo taken from the well head. What appears to be Canada thistle rosettes evident at the well head. This is a Colorado State listed noxious weed.



Photo 4: Photo taken from the northwest anchor, facing east. Photo shows what appears to be Canada thistle rosettes evident at the northwest and northeastern anchors. This is a Colorado State listed noxious weed.