

Inspection Photos

4/24/2019

Operator: BENCHMARK ENERGY LLC - 10380

Location ID: 312210

Inspection Doc. Number: 682504805

Logan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: BENCHMARK ENERGY LLC - 10380
Location ID: 312210



Photo 1: Photo taken from the west end of the location, facing east. Photo shows overview of the location. Undesirable weedy plant species such as kochia and salsola sp. have established on areas adjacent to, and bare areas beyond, the well head, .



Photo 2: Photo taken from the north end of the location. Photo shows what appears to be Musk thistle rosettes evident on the location. This is a Colorado State listed noxious weed.

Inspection Photos
Operator: BENCHMARK ENERGY LLC - 10380
Location ID: 312210



Photo 3: Photo taken from the north end of the location. Photo shows what appears to be Musk thistle rosettes evident on the location. This is a Colorado State listed noxious weed.



Photo 4: Photo taken from the north end of the location, facing south. Photo shows areas of the location that predominantly vegetated by undesirable weedy plant species such as Kochia and Salsola sp.