

Inspection Photos
Location Name: Nordstrom #3-9
Location ID: 321506



Photo 1 Well is P&A Well head appears to be removed. Storm water: No BMP's appear to be in place during the removal of production equipment during P&A process.

Photo 2 loc pic open hole. No BMP's appear to be in place during the removal of production equipment during P&A process.

Inspection Photos
Location Name: Nordstrom #3-9
Location ID: 321506



Colorado Oil and Gas Conservation Commission
39.98232, -105.00885, 1595.2m
Apr 24, 2019 09:24:10

Photo 3 Loc pic. Storm water: No BMP's appear to be in place during the removal of production equipment during P&A process.