

**Inspection Photos**  
**Location Name: Nordstrom #1-9**  
**Location ID: 321498**



**Photo 1 WH. Well is TA production equipment and flow lines have been removed from WH. Missing WH sign.**



**Photo 2 Sep/Meter house. Unused equipment: snow fence, telemetry equipment and steel fence.**

**Inspection Photos**  
**Location Name: Nordstrom #1-9**  
**Location ID: 321498**



**Photo 3 TNK BTRY**