

Inspection Photos
Location Name: Ehler#34-11-1
Location ID: 320309



Photo 1 WH



Photo 2 sep/meter house

Inspection Photos
Location Name: Ehler#34-11-1
Location ID: 320309



Photo 3 Unmarked Guy line anchor



Photo 4 TNK BTRY

Inspection Photos
Location Name: Ehler#34-11-1
Location ID: 320309



Photo 5 NFPA sticker faded



Photo 6 separator located in flood plain not properly anchored.

Inspection Photos
Location Name: Ehler#34-11-1
Location ID: 320309



Photo 7 trash: PVC pipe



Photo 8 tanks located in flood plain not properly anchored.