

COMPLIANCE FOLLOW UP FORM

INFORMATION

Name celkins@gobrainstorm.net
Date Tue Apr 09 2019
Well Name JACQUEZ, THOMAS GAS UNIT E 1
Select State Colorado
Work type COGCC Inspection AR
Action Complete Compliance Inspection Actions
Other
Clean up Operator Debris
Clean Up Contaminated Soils
Replaced/Repaired Tank Signs

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos

