

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/18/2019

Submitted Date:

04/18/2019

Document Number:

696100803

FIELD INSPECTION FORM

Loc ID 310232 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291652	WELL	SI	04/01/2017	GW	123-26107	70 RANCHUSX BB 35-03	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL, ABANDONED BATTERY** Inspection.
Well: PA
Battery: Abandoned & most equipment removed except for gas meter run & riser.
Abandoned Battery SE corner GPS coordinates: 40.360624, -104.406738
Reclamation progressing.

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused gas meter run, riser, & equipment at Abandoned Battery site. Refer to Rule 603.f for guidance when machinery required to remove equipment. See photos #2, 3.		
Corrective Action:	Remove unused gas meter run, riser, & equipment at Abandoned Battery site. Comply w/ Rule 603.f.		Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 291652 Type: WELL API Number: 123-26107 Status: SI Insp. Status: PA**Idle Well**Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well appears to have been P&A.
 Form 6 #401732256 indicates plugging date: 06/29/2018. (Approval Pending).
 Reclamation progressing.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>On THU APR 18, 2019 at approximately 13:30 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: 70 RANCHUSX BB-65N63W /35NENW Location ID: 310232 Location County: Weld County, Colorado While there, I observed: 1-Well(s) PA & Abandoned Battery . Routine Inspection.</p> <p>1 - Corrective Actions observed. 1.) Unused gas meter run, riser, & equipment at Abandoned Battery site. Refer to Rule 603.f for guidance when machinery required to remove equipment. See photos #2, 3. Remove unused gas meter run, riser, & equipment at Abandoned Battery site. Comply w/ Rule 603.f.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	04/18/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402014885	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4800513
696100804	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4800512