

Inspection Photos  
Location Name: Riggs 34-16  
Location ID: 327308



Colorado Oil and Gas Commission Conservation  
40.48071, -104.66535, 1425.0m, 359°  
Apr 24, 2019 14:01:31

Photo 1: Wellhead



Colorado Oil and Gas Commission Conservation  
40.47917, -104.66538, 1421.0m, 76°  
Apr 24, 2019 14:33:18

Photo 2: Tank Battery

Inspection Photos  
Location Name: Riggs 34-16  
Location ID: 327308




Photo 3: Rust on crude oil tank.



Photo 4: Chipped paint on produced water tank.