

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402000687

Date Received:

04/25/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Susana Lara-Mesa

Phone

303-825-4822

Email

slaramesa@kpk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 688401650

Inspection Date: 03/25/2019

FIR Submit Date: 03/25/2019

FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC

Company Number: 46290

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 336321

Location Name: DECHANT-STATE-62N67W Number: 16SWNW County: WELD

Qtrqr: SWN Sec: 16 Twp: 2N Range: 67W Meridian: 6
W

Latitude: 40.140140 Longitude: -104.902780

FACILITY - API Number: 05-123- -00 Facility ID: 239942

Facility Name: DECHANT-STATE Number: 1

Qtrqr: SWN Sec: 16 Twp: 2N Range: 67W Meridian: 6
W

Latitude: 40.140140 Longitude: -104.902780

CORRECTIVE ACTIONS:

1 CA# 123471

Corrective Action: Install sign to comply with Rule 210.d.

Date: 04/25/2019

Response: CA COMPLETED

Date of Completion: 04/24/2019

Operator Comment: Sign has been installed. Please see attached picture.

COGCC Decision: _____

COGCC
Representative:

2 CA# 123472

Corrective Action: Install sign to comply with Rule 210.d.

Date: 04/25/2019

Response: CA COMPLETED

Date of Completion: 04/24/2019

Operator
Comment: Sign has been installed. Please see attached picture.

COGCC Decision: _____

COGCC
Representative:

3 CA# 123473

Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e

Date: 04/25/2019

Response: CA COMPLETED

Date of Completion: 04/24/2019

Operator
Comment: Stained soil under load out line from crude oil tank has been removed. Please see attached picture.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Susana Lara-Mesa

Signed: _____

Title: VP of Engineering

Date: 4/25/2019 11:54:42 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402021514	CA PIC1
402021516	CA PIC2
402021517	CA PIC3

Total Attach: 3 Files