

Inspection Photos
Location Name: UPRR 23 PAN AM L #1
Location ID: 319929



Pic 1



Pic 2

Inspection Photos
Location Name: UPRR 23 PAN AM L #1
Location ID: 319929



Pic 3 Possible leak on separator.



Pic 4 Possible leak at wellhead

Inspection Photos
Location Name: UPRR 23 PAN AM L #1
Location ID: 319929



Pic 5 Possible leak at wellhead & Stained Soil.



Pic 6

Inspection Photos
Location Name: UPRR 23 PAN AM L #1
Location ID: 319929



Pic 7

