

Inspection Photos
Location Name: Ambush #24-22
Location ID: 320360



Pic 1

Pic 2 Unused pump jack, and other equipment.

Inspection Photos
Location Name: Ambush #24-22
Location ID: 320360



Pic 3, stained soil around motor.



Stained soil around wellhead.