

Inspection Photos

Location Name: FORK UNIT FEDERAL 7-12-1-2

Location ID: 05-103-08336

Inspection: 679703873

Gas leak



Photo 1. Location looking east.

Photo 2. Separator connection leaking gas at threads.



Inspection Photos

Location Name: FORK UNIT FEDERAL 7-12-1-2

Location ID: 05-103-08336

Inspection: 679703873



Photo 3. Storm water erosion along side of lease road entrance headed to pit.



Photo 4. Storm water erosion along side of road looking away from location.



Inspection Photos

Location Name: FORK UNIT FEDERAL 7-12-1-2

Location ID: 05-103-08336

Inspection: 679703873



Photo 5. Storm water from lease road entering pit.



Photo 6. Storm water entered pit and spilled over berm.

