

Inspection Photos

Location Name: HENDERSHOT-66N61W /25SENW

Location #: 317497



Photo #1

Hendershot #1 (05-123-05210) Wellsite

Shut-In | SI

Weeds



Photo #2

Hendershot #1 Battery

Shut-down

Weeds



Inspection Photos

Location Name: HENDERSHOT-66N61W /25SENW

Location #: 317497



Photo #3

Hendershot #1 Heater Treater

Stained Soil

from prior FIR



Photo #4

Hendershot #1 Heater Treater

Stained Soil – Not Addressed



Inspection Photos

Location Name: HENDERSHOT-66N61W /25SENW

Location #: 317497



Photo #5

Hendershot #1 Engine House

Stained Soil

from prior FIR



Photo #6

Hendershot #1 Engine House

Stained Soil – Not Addressed



Inspection Photos

Location Name: HENDERSHOT-66N61W /25SEnw

Location #: 317497



Photo #7

Hendershot #1 Heater Treater

Potential wildlife ingress

from prior FIR



Colorado Oil & Gas Conservation Commission
40.45999, -104.15872, 1403.0m, 80°
04/25/2019 01:22:29 PM

Photo #8

Hendershot #1 Heater Treater

Potential wildlife ingress

- Not Addressed



Inspection Photos

Location Name: HENDERSHOT-66N61W /25SENW

Location #: 317497



Photo #9

Hendershot #1 Tank Battery
Berm Integrity - Compromised
from prior FIR



Photo #10

Hendershot #1 Tank Battery
Berm Integrity - Compromised
- Not Addressed
Weeds



Inspection Photos

Location Name: HENDERSHOT-66N61W /25SENW

Location #: 317497



Photo #11

Hendershot #1 Wellsite

Unused Equipment

from prior FIR



Photo #12

Hendershot #1 Wellsite

Unused Equipment

- Not Addressed



Inspection Photos

Location Name: HENDERSHOT-66N61W /25SEW

Location #: 317497



Photo #13

Hendershot #1 Manifold Area

Unused Equipment

from prior FIR



Photo #14

Hendershot #1 Manifold Area

Unused Equipment

- Not Addressed



Inspection Photos

Location Name: HENDERSHOT-66N61W /25SENW

Location #: 317497



Photo #15

Hendershot #1 Pit Area

Weeds

from prior FIR



Photo #16

Hendershot #1 Pit Area

Weeds

- Not Addressed



Inspection Photos

Location Name: HENDERSHOT-66N61W /25SENW

Location #: 317497



Photo #17

Hendershot #1 Pit Area

Netting - Gaps

from prior FIR



Photo #18

Hendershot #1 Pit Area

Netting - Gaps

- Not Addressed



Inspection Photos

Location Name: HENDERSHOT-66N61W /25SENW

Location #: 317497



Photo #19

Hendershot #1 Wellsite

Unmarked Drum

