

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/26/2019

Submitted Date:

04/26/2019

Document Number:

692601711

FIELD INSPECTION FORM
 Loc ID 303027 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 24320

Name of Operator: DIAMOND OPERATING, INC.

Address: 6666 GUNPARK DR STE #200

City: BOULDER State: CO Zip: 80301

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|--------------|--------------------------|---------|
| Peterson, Dave | 303-494-4420 | davep@flatironenergy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 252284 | WELL | PR | 10/01/2018 | GW | 125-06154 | A. WELP 1 | PR |

General Comment:

Routine Inspection

| Location | | | | |
|--|--|--------|--|------------------|
| Lease Road: | | | | |
| Type | Access | | | |
| comment: | Access wellhead off of Hwy 385 | | | |
| Corrective Action | L | | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | | |
| Signs/Marker: | | | | |
| Type | TANK LABELS/PLACARDS | | | |
| Comment: | No labeling on water tank | | | |
| Corrective Action: | Install sign to comply with Rule 210.d. | | | Date: 07/26/2019 |
| Type | WELLHEAD | | | |
| Comment: | Lease sign mounted to meter shed | | | |
| Corrective Action: | | | | Date: |
| Emergency Contact Number: | | | | |
| Comment: | | | | Date: |
| Corrective Action: | | | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | | |
| Spills: | | | | |
| Type | Area | Volume | | |
| In Containment: No | | | | |
| Comment: | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |
| Fencing/: | | | | |
| Type | WELLHEAD | | | |
| Comment: | Metal panels around wellhead, meter sheds and VGS | | | |
| Corrective Action: | | | | Date: |
| Equipment: | | | | |
| | | | | corrective date |
| Type: Vertical Separator | # 6 | | | |
| Comment: | 5-Vertical gas separators 50% buried by meter sheds 1-Vertical gas separator next to wellhead | | | |
| Corrective Action: | | | | Date: |
| Type: Gas Meter Run | # 5 | | | |
| Comment: | Shared meter run for (A. Welp 1, 44-13, Odell 2-7, Rose 2-18) | | | |
| Corrective Action: | | | | Date: |
| Type: Ancillary equipment | # 1 | | | |
| Comment: | Telemetry equipment | | | |
| Corrective Action: | | | | Date: |
| Type: Plunger Lift | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Tanks and Berms:

| | | | | | | |
|--|---|----------|----------------|---------|-----------------------|--|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 1 | OTHER | PBV FIBERGLASS | | 39.879650,-102.244820 | |
| Comment: Fiberglass water tank 50% buried on east side of location | | | | | | |
| Corrective Action: | | | | | Date: | |

Paint

| | | |
|------------------|---------|--|
| Condition | | |
| Other (Content) | | |
| Other (Capacity) | 210bbls | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|---|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 252284 | Type: | WELL | API Number: | 125-06154 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing. Casing production. Central meter run for (A. Welp 1, 44-13, Odell 2-7, Rose 2 -18) | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | | | |

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT