

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/24/2019

Submitted Date:

04/29/2019

Document Number:

689500970**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 326774 Oakman, Kari 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Graber, Nikki		nikki.graber@state.co.us	
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245851	WELL	PA	11/09/2017	GW	123-13646	JEPSEN 3	EI

General Comment:

[This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.](#)

[Photos attached to document site condition at the time of inspection.](#)

Environmental**Spills/Releases:**

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Tank battery has been removed and backfilled with hydrocarbon impacted soil (Spill Report doc #402020896, 4/25/2019). Produced water vessel was removed under remediation project #13214. Stained soil with hydrocarbon odors were observed at the former battery location during inspection.

Corrective Action: Submit a supplemental form 27 with a project status update for the removal of hydrocarbon impacted soil.

Date: 05/24/2019

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689500971	Field Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4809734