

Inspection Photos
Location Name: Shannon-Roberts #1A
Location ID: 321499



Photo 1 improperly marked Guy line anchor.



Photo 2 improperly marked Guy line anchor.

Inspection Photos
Location Name: Shannon-Roberts #1A
Location ID: 321499



Photo 3 improperly marked Guy line anchor.