

Inspection Photos
Location Name: Moro Farms 34-29
Location ID: 419394



Photo 1: Wellhead; Debris needs to be removed. Wellhead sign installed.



Photo 2: Tank Battery

Inspection Photos
Location Name: Moro Farms 34-29
Location ID: 419394



Photo 3: Placard on produced water tank.



Photo 4: Debris/weeds need to be removed.