

# Inspection Photos

4/30/2019

Operator: FRITZLER RESOURCES INC - 31257

Location ID: 316908

Inspection Doc. Number: 682504835

Lincoln County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: FRITZLER RESOURCES INC - 31257  
Location ID: 316908



**Photo 1:** Photo taken from the well head. Photo shows stained/contaminated soils remain at wellhead.





**Photo 2:** Photo taken from the southeast corner of the well location. Previous inspection required operator to comply with rule 1003 and mark anchors. Photo shows anchor on the southeast end of location has not been marked in accordance with 1003.



Inspection Photos  
Operator: FRITZLER RESOURCES INC - 31257  
Location ID: 316908



**Photo 3:** Photos 3-7 taken from the adjacent areas of the well. Photos show equipment not needed for production remain stored on the location and interim areas.





**Photo 4:** See comments under photo 3.



**Photo 5** See comments under photo 3.





**Photo 6:** See comments under photo 3.

Inspection Photos  
Operator: FRITZLER RESOURCES INC - 31257  
Location ID: 316908



**Photo 7:** See comments under photo 3.

