

Inspection Photos  
Location Name: McCallum 148  
API: 05-057-06388



**Photo 1. Overview of location taken at entrance facing northwest.**

Inspection Photos  
Location Name: McCallum 148  
API: 05-057-06388



**Photo 2. Stained soil at pump jack motor.**



**Photo 3. Free fluid at pump jack motor.**