

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/01/2019

Submitted Date:

05/01/2019

Document Number:

688402062

**FIELD INSPECTION FORM**

Loc ID 336527 Inspector Name: Silver, Randy On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Findings:**

15 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email                         | Comment                         |
|--------------|-------|-------------------------------|---------------------------------|
| ,            |       | COGCCinspections@anadarko.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 297342      | WELL | SI     | 02/01/2019  | OW         | 123-27076 | CENTEX 10-25  | SI          |
| 297343      | WELL | SI     | 02/01/2019  | OW         | 123-27077 | CENTEX 16-25  | SI          |
| 297382      | WELL | SI     | 02/01/2019  | OW         | 123-27105 | CENTEX 40-25  | SI          |
| 297383      | WELL | SI     | 02/01/2019  | OW         | 123-27106 | CENTEX 24-25  | SI          |

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | WELLHEAD             |       |  |
| Comment:           | Adequate             |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           | Adequate             |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | BATTERY              |       |  |
| Comment:           | Adequate             |       |  |
| Corrective Action: |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |                   |       |  |
|--------------------|-------------------|-------|--|
| Type               | TANK BATTERY      |       |  |
| Comment:           | Steel             |       |  |
| Corrective Action: |                   | Date: |  |
| Type               | IGNITOR/COMBUSTOR |       |  |
| Comment:           | Steel             |       |  |
| Corrective Action: |                   | Date: |  |
| Type               | WELLHEAD          |       |  |
| Comment:           | Steel             |       |  |
| Corrective Action: |                   | Date: |  |
| Type               | SEPARATOR         |       |  |
| Comment:           | Steel             |       |  |
| Corrective Action: |                   | Date: |  |

**Equipment:**

|                       |     |       |                 |
|-----------------------|-----|-------|-----------------|
| Type: Bird Protectors | # 2 |       | corrective date |
| Comment:              |     |       |                 |
| Corrective Action:    |     | Date: |                 |
| Type: Plunger Lift    | # 4 |       |                 |

|                                   |                                   |  |       |
|-----------------------------------|-----------------------------------|--|-------|
| Comment:                          |                                   |  |       |
| Corrective Action:                |                                   |  | Date: |
| Type: Horizontal Heated Separator | # 1                               |  |       |
| Comment:                          |                                   |  |       |
| Corrective Action:                |                                   |  | Date: |
| Type: Gas Meter Run               | # 1                               |  |       |
| Comment:                          |                                   |  |       |
| Corrective Action:                |                                   |  | Date: |
| Type: Ancillary equipment         | # 1                               |  |       |
| Comment:                          | Telemetry equipment               |  |       |
| Corrective Action:                |                                   |  | Date: |
| Type: Emission Control Device     | # 1                               |  |       |
| Comment:                          |                                   |  |       |
| Corrective Action:                |                                   |  | Date: |
| Type: Bradenhead                  | # 4                               |  |       |
| Comment:                          | Appears to be plumbed to surface. |  |       |
| Corrective Action:                |                                   |  | Date: |

**Tanks and Berms:**

| Contents           | # | Capacity | Type           | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER     | 1 | OTHER    | FIBERGLASS AST |         | ,      |
| Comment:           |   |          |                |         |        |
| Corrective Action: |   |          |                |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) | 201bbl   |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity                                | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|---|---------------------|---------------------|-------------|
|                    |   |                     |                     |             |
| Comment:           | Shares containment with crude oil tanks |                     |                     |             |
| Corrective Action: |   |                     |                     | Date:       |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CRUDE OIL          | 3 | OTHER    | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) | 315bbl   |  |

|                    |  |
|--------------------|--|
| Other (Type) _____ |  |
|--------------------|--|

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

| Yes/No             | NO |  |       |
|--------------------|----|--|-------|
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

| Type               |  |       |
|--------------------|--|-------|
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 297342 Type: WELL API Number: 123-27076 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: SI. Form 6 Well abandonment Doc#401947572 on file with the COGCC.

Corrective Action:  Date:

Facility ID: 297343 Type: WELL API Number: 123-27077 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: SI

Corrective Action:  Date:

Facility ID: 297382 Type: WELL API Number: 123-27105 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment:

Corrective Action:  Date:

Facility ID: 297383 Type: WELL API Number: 123-27106 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: SI

Corrective Action:  Date:

**COGCC Comments**

| Comment                             | User    | Date       |
|-------------------------------------|---------|------------|
| <a href="#">Routine inspection.</a> | silverr | 05/01/2019 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 688402063    | loc pic     | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4812665">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4812665</a> |