

Pit Status Evaluation Form

Pit Overview:

Pit Name: DISTEL 21-2	Facility ID: 114849
Current Status: Unknown	Status Date: 9/23/1999
Current Operator: R & B ENERGY INC / 72932	
Updated Operator: OSAFOW OIL COMPANY - 66355	
Form 15 Pit Permit Doc #: NA	Permit Date: NA
Related Facilities: API # 05-013-06209 (Facility ID 206714), Location 379789	

County: Boulder			
Township: 2N	Range: 69W	Section: 21	QQ: NENE
Original Latitude/ Longitude: 40.128866 / -105.11439			
Updated Latitude/ Longitude: /			
Basis for Location Change:			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|---|------------------|
| <input type="checkbox"/> | Form 15 Pit Permit – Doc #: NA | Date: NA |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 580931 | Date: 7/17/1987 |
| | Doc #: 1080786 | Date: 11/10/1988 |
| | Doc #: 1080787 | Date: 6/26/1990 |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> | COGIS Document – Doc #: | Date: |
| <input type="checkbox"/> | Pit Inventory – Doc #: | Date: |
| <input type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: | |
| <input type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 9/23/1999

Timing of Pit Closure:

Well PA 5/18/1988, passed final inspection 6/26/1990 (pits backfilled, site clean)

Pit Status Review Summary:

Based on records review there is no evidence that there was a pit on location; inspection reports document a fiberglass tank on location. Well was plugged and passed final reclamation inspection 6/26/1990. Pit status has been changed to Closed.