

Inspection Photos
Location Name: J P Weise 2
API: 05-081-05291



Photo 1. Overview of location taken at entrance facing northwest. Wattles as debris visible around land farm area between tank and pump jack.