

Inspection Photos
Location Name: Sutton #41-21
Location ID: 332235



Photo 1 WH



Photo 2 TNK BTRY

Inspection Photos
Location Name: Sutton #41-21
Location ID: 332235



Photo 3 Produced water tank appears to have floated out of ground.



Photo 4 Produced water tank appears to have floated out of ground. Possible under ground issues.