

Final Reclamation Inspection

May 2, 2019

Operator: PDC ENERGY INC - 69175

API: 05-123-19318

Inspection Document #: 697500060

Weld County, CO

SWSW Section 32 T6N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: EHRlich #14-32
API: 05-123-19318



Photo 1. Photo taken from the tank battery location, facing North. Operator has failed to remove all equipment within 3 months of plugging operations.