

Final Reclamation Inspection

May 2, 2019

Operator: NOBLE ENERGY INC - #100322

Location ID: 322772

Inspection Document #: 697500067

Weld County, CO

NWNE Section 26 T4N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: RASSMUSSEN #1
Location ID: 322772



Photo 1. Photo taken within the PA well location, facing South. Operator has failed to perform Final Reclamation activities and remove equipment from the location.

Inspection Photos
Location Name: RASSMUSSEN #1
Location ID: 322772



Photo 2. Photo taken within the PA well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: RASSMUSSEN #1
Location ID: 322772



Photo 3. Photo taken within the PA well location, facing North. See comments under Photo 1.