

Final Reclamation Inspection

May 2, 2019

Operator: NOBLE ENERGY INC - #100322

Location ID: 329929

Inspection Document #: 697500069

Weld County, CO

SWNE Section 23 T4N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: UPV #23-714
Location ID: 329929



Photo 1. Photo taken within the PA well location, facing South. Well location does not meet Rule 1004 standards. There was little, to no, desirable vegetation observed at the well location.

Inspection Photos
Location Name: UPV #23-714
Location ID: 329929



Photo 2. Reference photo taken just west of the PA well location, facing West. See comments under Photo 1.