

Location Name: Coors 4-15

Location ID: 05-103-08599

Inspection: 679703965



Photo 1. Location looking west.



Location Name: Coors 4-15

Location ID: 05-103-08599

Inspection: 679703965



Photo 2. Valve open venting gas.

Photo 3. Well head.

