

BMC B Pad
12D-18-07-95
Api. # 05-045-23310
Inspection # 689703109



BMC B Pad
12D-18-07-95
Api. # 05-045-23310
Inspection # 689703109



Capped conductor in open cellar.

BMC B Pad
12D-18-07-95
Api. # 05-045-23310
Inspection # 689703109



Sediment build up in access road ditch into location

BMC B Pad
12D-18-07-95
Api. # 05-045-23310
Inspection # 689703109



Weed debris have been cleared from behind separators.

BMC B Pad
12D-18-07-95
Api. # 05-045-23310
Inspection # 689703109



Subsidence of postholes from removed sound walls.