

**Laramie Energy LLC**  
**Api # 05-077-10124**  
**Inspection # 696600033**



**Photo at entrance to location.**

Laramie Energy LLC  
Api # 05-077-10124  
Inspection # 696600033



Tank Battery



Wellhead



Laramie Energy LLC  
Api # 05-077-10124  
Inspection # 696600033



Axia Energy on tank label



Axia Energy on tank label, Capacity number is not legible

Laramie Energy LLC  
Api # 05-077-10124  
Inspection # 696600033



Axia energy on Wellhead sign



Tank label faded, not legible



**Laramie Energy LLC**  
**Api # 05-077-10124**  
**Inspection # 696600033**



**Heavy erosion on slope**



**Heavy erosion on slope**