

Inspection Photos

Location Name: JENNIFER J 21-28

API #: 05-071-09352

INSP. #:695100603



Colorado Oil & Gas Conservation Commission
37.0628, -104.6779, 2170.0m, 253°
2019/05/06 16:17:44



Colorado Oil & Gas Conservation Commission
37.17069, -104.50964, 358°
2019/05/06 16:17:04

PHOTO 1: LOCATION/ TRASH IN WELLHEAD HOUSE. COMPLY WITH RULE 603.f.

PHOTO 2: WELL SIGN/ OPERATOR ON POSTED WELL SIGN IS INACCURATE Install sign to comply with Rule 210.b.