

**Inspection Photos**  
**Location Name: Champlin 485 Amoco #1**  
**Location ID: 320071**



**Pic 1 Unused equipment Submersible pump equip.**



**Pic 2**

**Inspection Photos**  
**Location Name: Champlin 485 Amoco #1**  
**Location ID: 320071**



**Pic 3 unused equip chemical tank.**



**Pic 4**



**Inspection Photos**  
**Location Name: Champlin 485 Amoco #1**  
**Location ID: 320071**



**Pic 5 stained soil possible leak.**



**Pic 6**

**Inspection Photos**  
**Location Name: Champlin 485 Amoco #1**  
**Location ID: 320071**



**Pic 7 water pooled in water tank containment, possible leak.**



**Pic 8 pit no netting over pit.**



**Inspection Photos**  
**Location Name: Champlin 485 Amoco #1**  
**Location ID: 320071**



**Pic 9 pit with no net.**



**Pic 10**