

# Final Reclamation Inspection

May 6, 2019

Operator: HARSH INTERNATIONAL INC - 38470

API #: 05-123-29125

Inspection Document #: 697500076

Weld County, CO

NENE Section 6 T6N R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: HARSH #41-6  
API #: 05-123-29125



**Photo 1.** Photo taken from a portion of the access road, facing West. Access road is evident and has not been reclaimed per Rule 1004. It does not appear that the Operator has performed final reclamation activities throughout the access road. Reference area vegetation consists mostly of Crested wheatgrass and Smooth brome.



Inspection Photos  
Location Name: HARSH #41-6  
API #: 05-123-29125



**Photo 2.** Photo taken from the access road. Photo illustrates Cheatgrass and Kochia.



Inspection Photos  
Location Name: HARSH #41-6  
API #: 05-123-29125



**Photo 3.** Photo taken from another portion of the access road, facing West. See comments under Photo 1.



Inspection Photos  
Location Name: HARSH #41-6  
API #: 05-123-29125



**Photo 4.** Photo taken from the well location. Photo illustrates subsidence at the wellhead and vegetation around the wellhead is not reflective of reference area vegetation.



Inspection Photos  
Location Name: HARSH #41-6  
API #: 05-123-29125



**Photo 5.** Reference photo taken east of the well location, facing East.