

Inspection Photos

API: 05-055-06243

Operator: PETROGLYPH OPERATING CO

Inspection Date: 5/6/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-055-06243 | Date: 5/6/2019

Inspection Photos



Photo 1. Facing west along the beginning reclaimed access road. There is a pile of old straw with blue/red twine.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-055-06243 | Date: 5/6/2019

Inspection Photos



Photo 2. Facing northwest along the reclaimed access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06243 | Date: 5/6/2019

Inspection Photos



Photo 3. Facing west toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06243 | Date: 5/6/2019

Inspection Photos



Photo 4. Facing west toward the reclaimed location. Vegetation appears to be established with Spocry, Passmi, Grisqu, and other desirable species.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-055-06243 | Date: 5/6/2019

Inspection Photos



Photo 5. Facing east toward the reclaimed location. Vegetation appears to be established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06243 | Date: 5/6/2019