

Inspection Photos

5/06/2019

Operator: GRAND MESA OPERATING CO #
35080

Location ID: 456610

Inspection Doc. Number: 696200007
Lincoln County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos

Operator Name: GRAND MESA OPERATING CO # 35080

Location ID: 456610



Photo 1: Photo taken from the south end of the location, facing south. Photo shows erosion degradation occurring on the south end of the location. 6 foot measuring stick for reference.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: GRAND MESA OPERATING CO # 35080

Location ID: 456610



Photo 2: Photo taken from the south end of the location, facing west. Photo shows erosion degradation occurring on the south end of the location. 6 foot measuring stick for reference.

Inspection Photos

Operator Name: GRAND MESA OPERATING CO # 35080

Location ID: 456610



Photo 3: Photo taken from the south end of the location, facing north. Photo shows erosion degradation occurring on the south end of the location. 6 foot measuring stick for reference.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: GRAND MESA OPERATING CO # 35080

Location ID: 456610



Photo 4: Photo taken from the south end of the location, facing west. Photos 4-7 provide an overview of the location from west, northwest, northeast to east. Photos shows interim reclamation activities do not yet appear to have been conducted on the location.

Inspection Photos

Operator Name: GRAND MESA OPERATING CO # 35080

Location ID: 456610



Photo 5: See comments under photo 4.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: GRAND MESA OPERATING CO # 35080
Location ID: 456610



Photo 6: See comments under photo 4.

Inspection Photos

Operator Name: GRAND MESA OPERATING CO # 35080

Location ID: 456610



Photo 7: See comments under photo 4.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: GRAND MESA OPERATING CO # 35080

Location ID: 456610



Photo 8: Photo taken from the west end of the location, facing north. Photo shows straw bale wattles. BMPs appear to be in proper functioning condition.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: GRAND MESA OPERATING CO # 35080

Location ID: 456610



Photo 9: Photo taken from the west end of the location, facing east. Photo shows erosion degradation occurring on slopes of the soil stockpile and sediment deposition.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: GRAND MESA OPERATING CO # 35080

Location ID: 456610



Photo 10: Photo taken from the west end of the location, facing south. Photo shows erosion degradation occurring on slopes of the soil stockpile and sediment deposition. Surface roughening (ripping) appears to be catching the runoff from the stockpile mitigating any sediment transport off-site. Continue to monitor and manage location for stormwater and conduct maintenance as needed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: GRAND MESA OPERATING CO # 35080

Location ID: 456610



Photo 11: Photo taken from the northwest corner of the location, facing east. Photo shows the berm at the perimeter of the pad, and the ditch/berm at the perimeter of the location. Photo also shows tracking on slopes. BMPs appear to be in proper functioning condition.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources